


THERMOCOUPLE TEMPERATURE LARGE DISPLAY

GBMT

FEATURES

- Accuracy: $\pm 0.2\%$ F.S. ± 0.5 °C (Cold junction compensation)
- Measuring Temperature (TC) sensors for K, J, E, R, S, B, T
- High brightness LED display range: -19999~99999
- Parameters setting by **infrared remote control**
- 1 Control output 1~3 Alarms (Hi or Lo programmable) output / Analog output (15 bit resolution) / RS-485 communication optional (The above options can exist together)
- Invisible wire connection, easily installation




ORDER INFORMATION: GBMT - [Code 1] - [Code 2] - [Code 3] - [Code 4] [Code 5] [Code 6] [Code 7]

Code 1	Digits	Code 2	Input Type	Code 3	Aux. Power	Code 4	Control Output	Code 5	Alarm Output	Code 6	Analog Output	Code 7	RS-485
3	3 Digits	B	200~1800°C	A	AC/DC 100~240V	N	None	N	None	N	None	N	None
4	4 Digits	E	-185~900°C	D	AC/DC 22~60V	Y	1 Control	R1	1 Relay	A	4~20mA	Y	Modbus-RTU
5	5 Digits	J	-200~200°C					R2	2 Relays	V	0~10V		
O	Option	K	-200~1360°C					R3	3 Relays	L	LOOP POWER:15-30Vdc 4-20mA out put		
		R	0~1760°C							O	Option		
		S	0~1750°C										
		T	-200~395°C										


SPECIFICATION

- ◆ Accuracy: $\pm 0.2\%$ F.S., ± 0.5 °C (Cold junction compensation)
- ◆ Display Screen: High brightness red LED; 10cm (4")
- ◆ Sampling Time: 60 cycles / sec
- ◆ Display Range: -19999~99999
- ◆ Zero Adjustment: -19999~99999
- ◆ Over Range Indication: do / io or -do / -io
- ◆ Polarity Indication: Automatic with "-" indication
- ◆ Parameters Setting: Infrared Remote Control
- ◆ Back Up Memory: EEPROM
- ◆ Alarm Action: " \geq (Hi) on" or " $<$ (Lo) on"
- ◆ Alarm Run Delay Time: 0~99 sec
- ◆ Relay Contact: AC 277V / 7A; DC 30V / 7A
- ◆ Analog Output Resolution: 15 bit
- ◆ Output Response Time: < 250 msec (0~90%)
- ◆ Output Capability: Voltage Output: < 20 mA
Current Output: < 10 V
- ◆ Communication: RS-485 Modbus RTU mode
- ◆ Baud Rate: 19200 / 9600 / 4800 / 2400 bps
- ◆ Temperature Coefficient: 100ppm / °C (0~60°C)
- ◆ Operating Temperature: 0~60°C
- ◆ Operating Humidity: 20~90% RH (non-condensing)
- ◆ Storage Temperature: -10~70°C
- ◆ Storage Humidity: 20~90% RH (non-condensing)
- ◆ Power Supply: AC/DC 100~240V; AC/DC 22~60V
- ◆ Power Consumption: < 10 VA (all functions output)
- ◆ Surge Test: 1.5kVac / 1min (Input / Power)
- ◆ Input Impedence: Voltage: > 2 V for 20k Ω / V; ≤ 2 V for > 200 M Ω
Current: ≥ 0.2 A at 100mV; < 0.2 A at 1V


SIDE PANEL & KEY FUNCTIONS



WIRING





DIMENSION



* Please understand key indicators & functions at the first operation.

FRONT PANEL & KEY FUNCTIONS




- ID Confirmed Key
- Up Key
- Shift Key
- Down Key
- Enter Key or Save Key
- ID Display Key
- Reset Key
- No Function

Key Name	Symbol	Descriptions
ID Confirmed Key		1. In the measuring status, press this key can enter to ID confirmed page. 2. In the parameter setting, press this key can back to the measuring page.
Enter Key & Save Key	ENT	1. In the measuring status, press this key can enter to parameter pages. 2. In the parameter setting, press this key can save the value & go to next parameter.
Shift Key		1. In the parameter setting, press this key can move the cursor left.
Up Key		1. In the parameter setting, press this key can increase the digits.
Down Key		1. In the parameter setting, press this key can decrease the digits.

- ** 1. The following block charts are parameters codes, parameter codes & parameters will alternate flashing if the parameters can be modified.
 2. To modify the parameters, please press //, and press ENT to save the parameter after the modification.
 3. Please don't forget the new pass code after modification.
 4. In any pages, press , or don't press any keys for 2 minutes that will back to measuring status.

PROGRAMMING MODE OPERATING PROCEDURES



Display	Descriptions	Default
System Setting Group Procedures		
SYS		
TYP	Sensor Type Setting (TYPE)	Show the temperature sensor type. PS: Please don't forget the new pass code after modification.
		Customers specify
DP	Decimal Point Setting (dP)	Select decimal point (0, 1, 2, 3, 4). EX: if the value shows "0.00" that means the decimal point is 2 digits.
		Customers specify
UNI	Temperature Unit Setting (unit)	Select the units (°C or °F).
		Customers specify
CJC	Cold Junction Compensation (CJC)	Switch Cold Junction Compensation ON("no") PS: If setting "YES", the display value would not include the terminal's temperature.
		NO
AVG	Display Average Setting (AvG)	Modify display average number (1~99). PS: Please use this function for stable display value when input signal is unstable.
		005
COD	Pass Code Setting (Cod)	Modify pass code (0~19999). PS: Please don't forget the new pass code after modification.
		000
LOC	Key Lock Setting (LoC)	Lock the keys only can view the setting but not modify any values. PS: no (unlock), YES ("ENT" unlock, others lock).
		NO
ID	Identification Setting (id)	Modify identification (00~99). PS: If the ID is 00; Meter can received any Infrared Control.
		000

Display	Descriptions	Default
Alarm Setting Group Procedures		
ROP Press: ENT ↓	Alarm Setting Page (roP) The following steps are only available for alarm output.	
SP Press: ENT ↓	Control Setpoint (SP) Modify temperature control setpoint.	000
AL1 AL2 AL3 Press: ENT ↓	Alarm 1 (AI1) Alarm 2 (AI2) Alarm 3 (AI3) Action Setpoint Setting Modify alarm action setpoint.	000
ACT Press: ENT ↓	Control Action (ACT) Modify Control action how temperature value is \geq (Hi) or $<$ (Lo) the control setpoint	HI
AC1 AC2 AC3 Press: ENT ↓	Alarm 1 (Act1) Alarm 2 (Act2) Alarm 3 (Act3) Alarm Action Setting Modify alarm action how temperature value is \geq (Hi) or $<$ (Lo) or (Go) the alarm setpoint	HI
P.B Press: ENT ↓	Proportion Control Percentage (P.b) Modify proportion control percentage(0~999).	000
HY1 HY2 HY3 Press: ENT ↓	Hysteresis 1 (HYS1) Hysteresis 2 (HYS2) Hysteresis 3 (HYS3) Alarm Hysteresis Setting Modify the value, when alarm runs lower or higher display value (depends on alarm action). Alarm setpoint \pm this range (0~999) will turn off the alarm.	000
CTI Press: ENT ↓	Proportion Time (C.time) Modify proportion time (0~99 sec).	00
DE1 DE2 DE3 Press: ENT ↓	Delay Time 1 (dEL1) Delay Time 2 (dEL2) Delay Time 3 (dEL3) Alarm Run Delay Setting Modify the value, when the display value reach the alarm value that need to wait for this time (0~99 sec) for alarm action.	00
A/O Setting Group Procedures		
AOP Press: ENT ↓	A/O Setting Page (AoP) The following steps are only available for analog output.	
POL Press: ENT ↓	A/O Polarity Setting (PoLAr) PS : Voltage output , NO: positive pole output (0~+10V) YES: positive & negative pole output (-10~+10V)	NO
ANL Press: ENT ↓	A/O Low Scale Setting (AnLo) Adjust A/O low scale to correspond to the display value EX : A/O is 0~10V, the display is 10.0 to output 0V, this value must be set for 10.0.	000
ANH Press: ENT ↓	A/O Hi Scale Setting (AnHi) Adjust A/O hi scale to correspond to the display value EX : A/O is 0~10V, the display is 90.0 to output 10V, this value must be set for 90.0.	999

Display	Descriptions	Default
RS485 Setting Group Procedures		
DOP Press: ENT ↓	RS485 Setting Page (doP) The following steps are only available for RS-485.	
ADD Press: ENT ↓	Address Setting (Addr) Modify address (0~255).	000
BAU Press: ENT ↓	Baud Rate Setting (bAUd) Select baud rate (38400/19200/9600/4800).	384
PAR Press: ENT ↓	Parity Setting (PAri) Select parity (n.8.2/n.8.1/even/odd).	n.8.2.
Input / Output Adjustment Procedures		
ADJ Press: ENT ↓	Adjustment Setting Page (ADJ) Adjustment setting page	
C.OF Press: ENT ↓	CJC Offset Setting (COF) Modify the CJC offset value (-199~999).	000
R.OF Press: ENT ↓	Control Offset Setting (ROF) Modify the control offset value (-199~999).	000
DOF Press: ENT ↓	Display Offset Setting (DOF) Modify the display offset value (-199~999).	000
D.GA Press: ENT ↓	Display Gain Setting (dGA) Modify the display gain value (-199~999).	000
A.OF Press: ENT ↓	A/O Offset Setting (AoF) Modify the analog output offset value (-999~999).	000
A.GA Press: ENT ↓	A/O Gain Setting (AGA) Modify the analog output gain value (-999~999).	000

Error Code of Self-Diagnosis		
Display	Descriptions	
IO	Input signal is over 120% of input range.	
-IO	Input signal is under -20% of input range.	
DO	Input signal is over 180% of input range or meter error.	
-DO	Input signal is over display range (99999)	
ADE	Input signal is under display range (-19999)	
E00	EEPROM reading/writing suffers the interference (about 1 million times).	
**Please check the wiring connection is correct first, if the problem still exist, please return the meter to the factory.		